

Between-Subjects Factors

		Value Label	N
machine	1.00	machine 1	20
	2.00	machine 2	20
supplier	1.00	supplier 1	10
	2.00	supplier 2	10
	3.00	supplier 3	10
	4.00	supplier 4	10

Tests of Between-Subjects Effects

Dependent Variable: component

Source	Type III Sum of Squares	df	Mean Square	F	Sig.
Model	13687.600 ^a	8	1710.950	72.962	.000
machine	8.100	1	8.100	.345	.561
supplier	36.500	3	12.167	.519	.672
machine * supplier	26.900	3	8.967	.382	.766
Error	750.400	32	23.450		
Total	14438.000	40			

a. R Squared = .948 (Adjusted R Squared = .935)

Figure 14.32